

B135 7610-621

Lt. 63 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$52.00

## TYPE BUILDINGS

Greenhaven 70 #1

PERMIT NO. <b>E-5976</b>	LOCATION <b>37 - Starlit Circle</b>	<b>A-3</b>
DATE <b>Jan. 16-64</b>	PURPOSE <b>Const. dwelling &amp; attached garage</b>	
ZONE <b>R-1</b>	OWNER <b>Waren Mayes</b>	<b>5736-Mariposa Avenue</b>
	ARCH'T <b>W. Mayes</b>	<b>967-6525</b>
	CONT'R <b>Same</b>	

VAL. <b>\$14,500.</b>	STORIES <b>1</b>	ROOMS <b>6</b>	APTS. <b>460-gar.</b>	SIZE <b>1,468 sq.ft.</b>
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM	<i>1-24-64</i>	<i>Hammers</i>		
JOIST	<i>2-5-64</i>	<i>Hammers</i>		
FRAME	<i>3-17-64</i>	<i>Hammers</i>		
SHEET ROCK	<i>3-26-64</i>	<i>Hammers</i>		
FINAL	<i>6-1-64</i>	<i>Perli</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
2.4.64	St slab                      Hammers

COMPLETE  
AND OK

INSPECTOR