

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	5
4637 Beechnut Way		4637 Beechnut Way		5	
LEGAL DESCRIPTION					
Southgate Meadows #4 Lot 253					
TITLE AND NAME		ADDRESS		ZIP	
Besco		2777 Alvarado St.		95833	
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.	
Besco					
MECH. CONTR.		ARCH. ENGR.		OWNER	
				Valbrook, Inc.	
COST. LOAN LENDER		ISSUED BY			
		DATE			
BLDG. WIDTH		BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.
					AREA 1st FLOOR
			1		TOTAL AREA
					C.S.D.
					C.I. CASE
					CENSUS TRCT. NO.
					1,404
					EXISTING BLDG'S SAME LOT
					HOW USED
					TREES RMVD.
					SPACES
					PARK'G REQ.
					REAR YARDS
					SET BACK REQ.
NATURE OF WORK: Const., dwelling & gar. Plan 241 1B					
PERMIT NO. S.P. - E-9774		MICROFILM RECORD			
ISSUED BY		PLANS AND APPLICATION			
		REEL NO. 162		FRAME NO. 321	
VALUATION		INSPECTION RECORD		JOB FILE	
\$ 13,600.00		REEL NO. 147A		FRAME NO. 234	
ISSUANCE DATE 3-2-65		R.U.F. FEE			
		\$			
SM.I. FEE		\$			
PLAN CK. FEE		\$			
SEWER INCL. FEE		\$			
PERMIT FEE		\$ 49.00			
TOTAL FEES		\$			

Dwelling

REMARKS AND/OR VARIANCES