

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
4637 Beechnut Way		5			
LEGAL DESCRIPTION					
Southgate Meadows #4 Lot 253					
TITLE AND NAME		ADDRESS		ZIP	
Besco		2777 Alvarado St.			
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.	
Besco					
MECH. CONTR.		ARCH. ENGR.		OWNER	
				Valbrook, Inc.	
COST. LOAN LENDER		ISSUED BY		DATE	
		C.L. CASE		C.S.D.	
		TOTAL AREA		1,404	
		EXISTING BLDG'S SAME LOT		HOW USED	
		REAR YARDS		SIDE YARDS	
		SET BACK REQ.		USE ZONE	
		1			
		PARK'G REQ.		SPACES	
		TREES RMVD.		EXISTING BLDG'S SAME LOT	
		ROOF CONSTR.		AREA 1st FLOOR	
		NO. OF STORIES		TOTAL HEIGHT	
		1			
		BLDG. LENGTH		BLDG. WIDTH	
NATURE OF WORK: Const. dwelling & gar. Plan 241 1B					
PERMIT NO. S.P. - E-9774		MICROFILM RECORD			
ISSUED BY		PLANS AND APPLICATION			
3-2-65		REEL NO. 162 TO			
VALUATION		INSPECTION RECORD			
\$ 13,600.00		REEL NO. 147 TO			
R.O.P. FEE		JOB FILE			
\$		FRAME NO. 321 TO			
S.M.I. FEE		FRAME NO. 321 TO			
\$					
PLAN CK. FEE					
\$					
SEWER INCL. FEE					
\$					
PERMIT FEE		REMARKS AND/OR VARIANCES			
\$ 49.00		Dwelling			
TOTAL FEES					
\$					