

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>6971</i>	LOCATION <i>6111 Eastern Green</i>		
DATE <i>9/23/34</i>	PURPOSE <i>Auto. Hall to Garage</i>	ROOMS	APTS. <i>1</i>
ZONE	OWNER <i>E. J. Barron</i>	PHONE	
	ARCH'T		
	CONT'R <i>Basements</i>		
	VAL. <i>117 -</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT			ROOF			Cement Tests
		1	2	3				
EX WALL	Jolts					Chimneys		
	Beams and Girders					Fire Place		
Int Wall	Studs and Columns					Gas Water Heater		
	Bridging Fire Stops					Heater Closet		
Piers	Fire Escape Stand Pipes					Furnace		Window Courts
	Metal Lath					Boiler Room		
	Stairs					Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
9/24/30	Made Inspection of Addition to rear of Pri. Garage
9/27/30	Notified Contractor Windows in rear wall less than 3/4" from line. Contractor did so and filled in opening with Ext of Rear Wall Metal Laths & plaster.
9/29/30	Addition to Garage completed O.K. R.H. Campbell
9/29/30	COMPLETED AND O.K. Alden H. Campbell INSPECTOR