

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>6971</i>	LOCATION <i>6111 Eastern Green</i>		
DATE <i>9/23/34</i>	PURPOSE <i>Auto. Hall to Garage</i>	ROOMS	APTS. <i>1</i>
ZONE	OWNER <i>E. J. Barron</i>	PHONE	
	ARCH'T		
	CONT'R <i>Basements</i>		
	VAL. <i>117 -</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF	Chimneys		Cement Tests
EX WALL	Jolsts								
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
9/24/30	Made Inspection of Addition to rear of Pri. Garage
9/27/30	Notified Contractor Windows in rear wall less than 3/4" from line. Contractor did so and filled in opening with Ext of Rear Wall Metal Laths & plaster.
9/29/30	Addition to Garage completed O.K. R.H. Campbell
9/29/30	COMPLETED AND O.K. Alden H. Campbell INSPECTOR