

R 230 E 88-96

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD						\$55.00
N 75' of E-160' of San Juan Rd. W of Northstead Dr.						TYPE BUILDINGS Northgate #4
PERMIT NO.	LOCATION					A-6
F-9148	3335 - North Stead Dr.					
DATE	PURPOSE					
Dec. 6-67	Const. dwlg. & att. garage					
ZONE	OWNER					
R-1	Peace Lutheran Church 925 San Juan Rd.					
	ARCH'T					
	925-0351					
	CONT'R					
	Owner same					
VAL.	STORIES		ROOMS	APTS.	SIZE	
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)	
FORM	12-7-67	Barbato				
JOIST	12-15-67	Barbato				
FRAME						
SHEET ROCK	3-5-68	Chapin			Certified 4-9-68	
FINAL	7-31-68	Chapin				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
8-14-64	PT. Braces missing in garage - Hall ceiling needs fix - stop no plans on job - see address - - Howard
	COMPLETE AND OK

INSPECTOR