

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-7342</i>	LOCATION <i>3735 - San Carlos Way</i>
DATE <i>11/3/37</i>	PURPOSE <i>New dwlg & garage</i>
ZONE <i>2 - 70m</i>	OWNER <i>Donthey W. Pierce</i>
	ARCH'T. <i>H. H. Pierce</i>
	CONTR. <i>H. H. Pierce</i>

VAL <i>3000</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-----------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>3000</i>
VENT SHAFTS		BOILER ROOMS	<i>884P</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>2350</i>
LATH		GAS VENTS	<i>/</i>
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS	
11-5-31	1 st	Insp Form & on Pickets
12-3-31	2 "	Frame " Pickets
12-17	3 "	Lath " Pickets

COMPLETE
AND O. K.

INSPECTOR