

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-7346</i>	LOCATION <i>1017 - 4<sup>th</sup> Street</i>			
DATE <i>1/30/39</i>	PURPOSE <i>Remodel store front</i>			
ZONE	OWNER <i>John Nicis</i>			
	ARCH'T. <i>Frank Lindry</i>			
VAL. <i>200</i>	CONTR. <i>Frank Lindry</i>			
	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH	<i>Wrecked</i>	GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE--

CONDITION OF WORK--REMARKS

2/10/59

2nd Insp. Frame in remodeling found and  
interior of safe. OK R.W. Campbell

COMPLETE  
AND O. K.

INSPECTOR