

P 288 F 333-358

Blk Bounded BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$326.50

by I & J, 3rd & 5th St TYPE BUILDINGS
(Redev. Project #4)

R 305 F 153-127 Gill

| | | |
|----------------------|--|---------|
| PERMIT NO. G-8418 | LOCATION 918 - 5th Street | A-2 (7) |
| DATE Sep 17-70 | PURPOSE Const. store & assembly building | |
| ZONE C-3 | OWNER Bing Kong Tong Assoc. 1400 21st Street | |
| | ARCHT H.F. Yee | |
| | CONTR F.J. Chapek Const. P.O. Box 8509 | |

| | | | | |
|-----------------|-----------|-------|-------|-------------------|
| VAL. \$200,000. | STORIES 3 | ROOMS | APTS. | SIZE 9,740-sq.ft. |
|-----------------|-----------|-------|-------|-------------------|

| | | | | |
|-------|------|--------------------------|---------------------|------------------------|
| INSP. | DATE | BLDG. TYPE III 1 hr. Spr | OCCUPANCY GROUP B-3 | PHONE (O) (C) 428-3912 |
|-------|------|--------------------------|---------------------|------------------------|

FORM 9-24-70 [Signature] 2-11-71 [Signature] (stairs)

JOIST

FRAME 12-1-70 [Signature]

SHEET ROCK 3-5-71 [Signature]

FINAL 1-15-71 Dana Fuller

certificates sent out

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|----------|---|
| 9-28-70 | Rk 30" 2' 00" Full |
| 9-24-70 | OK Bl position north & south |
| 9-23-70 | Weather OK south wall |
| 10-1-70 | Rk 31' 4" 2' 00" Full |
| 10-3-70 | OK wind - per note |
| 10-5-70 | Rk 31' 4" 2' 00" Full |
| 10-4-70 | Rk 31' 4" 2' 00" Full |
| 10-9-70 | Rk 31' 4" 2' 00" Full |
| 10-21-70 | Rk called out note |
| 10-22-70 | Rk 31' 4" 2' 00" Full |
| 10-23-70 | Rk 31' 4" 2' 00" Full |
| 10-24-70 | Rk 31' 4" 2' 00" Full |
| 10-24-70 | Rk 31' 4" 2' 00" Full |
| 11-4-70 | COMPLETE steel & p.p. walls based on note |
| 11-10-70 | AND OK walls to note DS 10-12' Inspector |

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$326.50

TYPE BUILDINGS

Card #2

| | | | | | |
|----------------------|------|--|-------|---------------------|---------------------------|
| PERMIT NO. G-8418 | | LOCATION 918 - 5th Street A-2 (7) | | | |
| DATE Sep. 17-70 | | PURPOSE Const. store & assembly building | | | |
| ZONE C-3 | | OWNER Bing Kong Tong Assoc. 1400 - 21st St | | | |
| | | ARCH'T H. F. Yee | | | |
| | | CONTR F J. Chapek Const. P.O. Box 8509 | | | |
| VAL. \$200,000. | | STORIES 3 | ROOMS | APTS. | SIZE 9,740-sq. ft. |
| INSP. | DATE | BLDG. TYPE III 1 Hr Spr. | | OCCUPANCY GROUP B-3 | PHONE (O) (C) 428-3912 |
| FORM | | F-2 | | | |
| JOIST | | | | | |
| FRAME | | | | | |
| SHEET ROCK | | | | | |
| FINAL | | | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|----------|---|
| 11/10/70 | OK on third type D.D 10-13' <i>Barbata</i> |
| 11-19-70 | columns steel not used by <i>Barbata</i> |
| 12-15-70 | OK columns <i>Barbata</i> |
| 1-31-71 | OK saw frame <i>Barbata</i> |
| 1-9-71 | OK partial bay nail <i>Hammer</i> |
| 2-1-71 | OK saw framing <i>Barbata</i> |
| 2-3-71 | OK slab - 1/2 thickness <i>Filled</i> |
| 2-5-71 | OK slab <i>Barbata</i> |
| 3-10-71 | OK exterior walking with only <i>Hammer</i> |
| 3-23-71 | OK partial frame <i>Hammer</i> |
| | |
| | |
| | |
| | |
| | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div> |

11-19-70
12-15-70
1-31-71
1-9-71
2-1-71
2-3-71
2-5-71
3-10-71
3-23-71