

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 8614 Fairbrook Way		INSPECTION AREA I	
LEGAL DESCRIPTION Lot 342 Glenbrook #4					
TITLE AND NAME Besco		ADDRESS Same		CITY LIC. NO.	
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.	
MECH. CONTR.		ARCH. ENGR.		OWNER Matbrook Inc.	
CERTIFICATE OF OCCUPANCY		2777-Alvarado St. San Leandro, Calif.			
ISSUED BY		DATE		CONST. LOAN LENDER	
ELECTRICAL BY		DATE		NO. OF STORIES	
PLUMBING BY		DATE		ROOMS	
MECHANICAL BY		DATE		AREA 1st FLOOR	
BUILDING BY		DATE		SPACES	
Calloway		3/3/67		494 gar.	
CITY LIC. NO.		ZIP		TREES RMVD.	
363-7315		Same		EXISTING BLDG'S SAME LOT	
TEL. NO.		CENSUS TRCT. NO.		HOW USED	
363-7315		1			

NATURE OF WORK:-		Const. dwelling & att. garage Plan 404	
ISSUED BY		MICROFILM RECORD	
PERMIT NO. S.P. - F-5758		PLANS AND APPLICATION	
ISSUANCE DATE		REEL NO. 206	
10/31/66		FRAME NO. - 045	
VALUATION		INSPECTION RECORD	
\$ 12,400.00		REEL NO.	
R.U.F. FEE		JOB FILE	
\$		REEL NO.	
S.M.I. FEE		FRAME NO. -	
\$		TO	
PLAN CK. FEE		TO	
\$		TO	
SEWER INCL. FEE		REMARKS AND/OR VARIANCES	
\$		Dwelling	
PERMIT FEE		498P 204 - 1st	
\$ 46.00			
TOTAL FEES			
\$			
\$			