

5342 F118

Lot 23

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$46.00

Larchmont Northgate #1 TYPE BUILDINGS R 234 F482-492

|                     |  |
|---------------------|--|
| PERMIT NO.<br>G-871 | LOCATION 3101 - Wiese Way A-6 (70.02)      |
| DATE<br>July-11-68  | PURPOSE Const. dwelling & garage. P. 82-X  |
| ZONE<br>R-1         | OWNER Larchmont Northgate No. 2 Sacto, Inn |
|                     | ARCH'T L. C. Major & Assoc. / Plaza.       |
|                     | CONT'R Owner Same                          |

|                |         |       |       |               |      |
|----------------|---------|-------|-------|---------------|------|
| VAL. \$12,100. | STORIES | ROOMS | APTS. | 380-gar.      | SIZE |
|                |         |       |       | 1,275 sq. ft. |      |

| INSP.      | DATE     | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
|------------|----------|------------|-----------------|---------------|
| FORM       | 8-26-68  | Hammond    |                 |               |
| JOIST      |          |            |                 |               |
| FRAME      | 8-27-68  | E. Hammond |                 |               |
| SHEET HOOK | 10-4-68  | E. Hammond |                 |               |
| FINAL      | 11/18/68 | E. Hammond |                 |               |

| DATE     | SPECIAL CONDITIONS OF WORK — REMARKS                      |
|----------|---|
| 8-24-67  | Mk slab <span style="float: right;">Summers</span>        |
| 11-13-67 | 720 square feet <span style="float: right;">Chapin</span> |
|          |   |
|          |   |
|          |   |
|          |   |
|          |   |
|          |   |
|          |   |
|          |   |
|          |   |
|          |   |

COMPLETE  
AND OK

INSPECTOR