

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>A-638</b>	LOCATION <b>To const service station 3815 - Stockton Blvd.</b>
DATE <b>JUN-5-33</b>	PURPOSE <b>Sacramento Methodist Episcopal Church</b>
ZONE <b>Lim. Retail</b>	OWNER <b>James Snapp, (Exec)</b>
	ARCH'T <b>"</b>
	CONT-R <b>"</b>

VAL. **30000**

STORIES

ROOMS

APTS.

SIZE

**14 X 24**

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
7/5/33	Foundation g.P.S.
7/19/33	2 <sup>ND</sup> INS.P. Frame In Service Station <sup>OK</sup> A.W. Campbell
7/26/33	3 <sup>RD</sup> INS.P. INT & EXT LOTS OK A.W. Campbell
8/25/33	4 <sup>TH</sup> INS.P. Service Station Completed A.W. Campbell
8/25/33	Issued Final Insp. & Certificate of Occupancy
	Street Cleaned up O.K. A.W. Campbell
8/25/33	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR