

K289 F423

E397 FR 1-135 ~~PLAN~~

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$74.00

TYPE BUILDINGS

1045 E 306 file

| | |
|----------------------|--|
| PERMIT NO. G-8741 | LOCATION 177 - Otto Circle A-4 (41) |
| DATE Oct. 9-70 | PURPOSE Construct addition to laundry service |
| ZONE | OWNER Dust-Tex Inc. Same |
| | ARCH'T Leo McGlade 2011 - Arden Way |
| | CONTR R & H Const. P.O. Box 9923 |

| | | | | |
|----------------|---------|-------|-------|------|
| VAL. \$20,000. | STORIES | ROOMS | APTS. | SIZE |
|----------------|---------|-------|-------|------|

| | | | | |
|-------|------|-----------------------|---------------------|------------------------|
| INSP. | DATE | BLDG. TYPE III No Hr. | OCCUPANCY GROUP F-2 | PHONE (O) (C) 422-4009 |
|-------|------|-----------------------|---------------------|------------------------|

FORM *10-13-70* *Correct*

JOIST

FRAME *1-27-71* *McCallroy*

SHEET ROCK

71c FINAL *1-27-71* *Finald by Storage* *McCallroy*

1-28-71

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--|
| 10-15-70 | Rk slab (Check) |
| 10-23-70 | Rk slab not made (Check) |
| 11/10/70 | Rk roof diaphragm - joints not checked correctly. glulox certificate (Check) |
| 11/2/70 | Re-insp roof diaphragm ok. (Check) |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |