

Lot #291 - BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$42.50				
S.L.P. Hills 23 Annex TYPE BUILDINGS <i>786 7598.208</i>				
PERMIT NO. D-9132	LOCATION 6800 - South Land Park Drive A-3			
DATE Jul 19-61	PURPOSE Const. dwelling & att. garage.			
ZONE R-1	OWNER Lee Basford			
	ARCH'T			
	CONT'R Owner		HI 6-4444	
VAL. \$15,700.	STORIES 1	ROOMS 6	APTS.	SIZE 1,660 sq.ft.
INSP.	DATE	INSPECTOR		
FORM	<i>7-21-61</i>	<i>Basford</i>		
JOIST	<i>8-1-61</i>	<i>Basford</i>		
FRAME	<i>8-23-61</i>	<i>Basford</i>		
LATH	<i>8-25-61</i>	<i>Basford</i>		
FINAL	<i>10-9-61</i>	<i>Jones</i>		

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
7-27-61	PT joint not ready. Joists over installed Joint does not have enough blocking. Plumbing did not block, filled with dirt of lower joint not enough cleaning. <i>Barlett's</i>
8-22-61	Plaster work done to 15 lb. <i>Barlett's</i> Joint spraying under there. R. proved
9-7-61	excessive amount of paint over <i>Barlett's</i> joint to be scraped off. <i>Barlett's</i>
9-8-61	broken studs to be removed <i>Barlett's</i>
COMPLETE AND OK	INSPECTOR