

Lot #291 - BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$42.50

S.L.P. Hills 23 Annex TYPE BUILDINGS *786 7598.208*

PERMIT NO. D-9132	LOCATION	6800 - South Land Park Drive A-3	
DATE Jul 19-61	PURPOSE	Const. dwelling & att. garage.	
ZONE R-1	OWNER	Lee Basford	
	ARCH'T		
	CONT'R	Owner	HI 6-4444

VAL.	\$15,700.	STORIES 1	ROOMS 6	APTS.	SIZE 1,660 sq.ft.
------	-----------	--------------	------------	-------	----------------------

INSP.	DATE	INSPECTOR
FORM	7-21-61	Basford
JOIST	8-1-61	Basford
FRAME	8-23-61	Basford
LATH	8-25-61	Basford
FINAL	10-9-61	Jones

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
7-27-61	PT joint not ready. Joists over installed Joint does not have enough blocking. Plumbing did not block, filled with dirt of lower joint not enough cleaning. <i>Barlett's</i>
8-22-61	Plaster work done to 15 lb. <i>Barlett's</i> Joint spraying under there. Ripped
9-7-61	excessive amount of paint over <i>Barlett's</i> joint to be scraped off. <i>Barlett's</i>
9-8-61	broken studs to be removed <i>Barlett's</i>
	COMPLETE AND OK INSPECTOR