

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

| | | | | | | | | | |
|------------------------|--------------|-------------------|----------------|--------------|----------------|-----------------|--------------------------|--------------------------|---------|
| PROPERTY PARCEL NO. | | JOB ADDRESS | | | | INSPECTION AREA | | FINAL INSPECTIONS | |
| | | 9 Birty Ct. | | | | 1 | | | |
| LEGAL DESCRIPTION | | | | OCCUP. GR. | CONST TYPE | VAR. NO. | FIRE ZONE | BUILDING BY | DATE |
| Glenbrook #10 Lot 1072 | | | | | | | | <i>Lauen</i> | 11-7-69 |
| TITLE AND NAME | | ADDRESS | | ZIP | CITY LIC. NO. | TEL. NO. | | ELECTRICAL BY | DATE |
| GEN. CONTR. Besco | | | | | | | | | |
| ELEC. CONTR. | | | | | | | | PLUMBING BY | DATE |
| PLBG. CONTR. | | | | | | | | | |
| MECH. CONTR. | | | | | | | | MECHANICAL BY | DATE |
| ARCH. ENGR. | | | | | | | | | |
| OWNER Center Dev. Inc. | | 2777 Alvarado St. | | | | | | CERTIFICATE OF OCCUPANCY | |
| CONST. LOAN LENDER | | | | | | | | ISSUED BY | DATE |
| BLDG. WIDTH | BLDG. LENGTH | TOTAL HEIGHT | NO. OF STORIES | ROOF CONSTR. | AREA 1st FLOOR | TOTAL AREA | C.S.D. | C.I. CASE | |
| | | | 1 | | | 1,376 | | | |
| SIDE YARDS | REAR YARDS | SET BACK REQ. | USE ZONE | PARK'G REQ. | SPACES | TREES RMVD. | EXISTING BLDG'S SAME LOT | HOW USED | |
| | | | | | | | | | |

NATURE OF WORK:- Const. dwelling and att. garage

| | | | | |
|--------------------------|--------------------------|--------------|----------------|--------|
| PERMIT NO. S.P. - G-3742 | MICROFILM RECORD | | | |
| ISSUED BY | | | | |
| ISSUANCE DATE 6-11-69 | PLANS AND APPLICATION | REEL NO. 262 | FRAME NO:- 20 | TO |
| VALUATION \$ 13,500.00 | INSPECTION RECORD | REEL NO. 416 | FRAME NO:- 537 | TO 538 |
| R.D.F. FEE \$ | JOB FILE | REEL NO. | FRAME NO:- | TO |
| S.M.I. FEE \$ | | | | |
| PLAN CK. FEE \$ | | | | |
| SEWER INCL. FEE \$ | | | | |
| PERMIT FEE \$ 49.00 | REMARKS AND/OR VARIANCES | | | |
| \$ | Dwelling | | | |
| \$ | | | | |
| TOTAL FEES \$ | | | | |

