

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

| | | | | | | | | |
|-----------------------------|--------------|--------------------|----------------------|--------------|----------------|-----------------|--------------------------|--|
| PROPERTY PARCEL NO. | | JOB ADDRESS | | | | INSPECTION AREA | FINAL INSPECTIONS | |
| | | 4546 Cedarwood Way | | | | 5 | | |
| LEGAL DESCRIPTION | | | OCCUP. GR. | CONST TYPE | VAR. NO. | FIRE ZONE | | |
| Lot 47 Southgate Meadows #1 | | | | | | | | |
| TITLE AND NAME | | 1/C | ADDRESS | | ZIP | CITY LIC. NO. | TEL. NO. | |
| GEN. CONTR. Besco | | | 4725 Thornton Avenue | | | | 543-3103 | |
| ELEC. CONTR. | | | | | | | | |
| PLBG. CONTR. | | | | | | | | |
| MECH. CONTR. | | | | | | | | |
| ARCH. ENGR. | | | | | | | | |
| OWNER Valbrook, Inc | | | 4725 Thornton Avenue | | | | | |
| CONST. LOAN LENDER | | | | | | | | |
| BLDG. WIDTH | BLDG. LENGTH | TOTAL HEIGHT | NO. OF STORIES | ROOF CONSTR. | AREA 1st FLOOR | TOTAL AREA | C.S.D. | |
| | | | 1 | | | | | |
| SIDE YARDS | REAR YARDS | SET BACK REQ. | USE ZONE | PARK'G REQ. | SPACES | TREES RMVD. | EXISTING BLDG'S SAME LOT | |
| | | | | | | | 472 gar 1,404 sq. ft. | |
| HOW USED | | | | | | | | |

NATURE OF WORK:-
 Const dwelling and garage Plan 241

| | | | |
|--------------------------|-----------------------|--------------|-----------------------|
| PERMIT NO. S.P. - E-5424 | MICROFILM RECORD | | |
| ISSUED BY | PLANS AND APPLICATION | REEL NO. 131 | FRAME NO:- 258 |
| ISSUANCE DATE 1-22-63 | INSPECTION RECORD | REEL NO. 128 | FRAME NO:- 613 TO 620 |
| VALUATION \$13,600 | JOB FILE | REEL NO. | FRAME NO:- TO |
| R.U.F. FEE \$ | | | |
| S.M.I. FEE \$ | | | |
| PLAN CK. FEE \$ | | | |
| SEWER INCL. FEE \$ | | | |
| PERMIT FEE \$49.00 | | | |
| \$ | | | |
| \$ | | | |
| TOTAL FEES \$ | | | |
| REMARKS AND/OR VARIANCES | | | |
| R 493F098 - final | | | |
| dwlg. | | | |

