

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
26 Dalby Court		5		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
Lot 335 Southgate Meadows #5					
TITLE AND NAME		ADDRESS		CITY LIC. NO.	
Besco		Same		483-4300	
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.	
MECH. CONTR.		ARCH. ENGR.		OWNER	
2777 Alvarado St. San Leandro		2777 Alvarado St. San Leandro		CONST. LOAN LENDER	
ISSUED BY		DATE		C.I. CASE	
Barbato		5/20/66			
ELECTRICAL BY		DATE		C.S.D.	
Barbato					
PLUMBING BY		DATE		CENSUS TRCT. NO.	
				13755-17	
MECHANICAL BY		DATE		EXISTING BLDG'S SAME LOT	
				HOW USED	
SIDE YARDS		REAR YARDS		SET BACK REQ.	
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT	
AREA 1st FLOOR		ROOF CONSTR.		NO. OF STORIES	
110-4ac.					
TOTAL AREA		C.S.D.		C.I. CASE	

NATURE OF WORK: Const. dwlg. & att. gar. Plan 504 IC

PERMIT NO., S.P.		F-3299	
ISSUED BY		MICROFILM RECORD	
ISSUANCE DATE		3/1/66	
VALUATION		\$ 13,500.00	
R.D.F. FEE		\$	
JOB FILE		REEL NO. 153	
FRAME NO. TO		484	
INSPECTION RECORD		REEL NO. 188	
FRAME NO. TO		138	
PLAN CK. FEE		\$	
SEWER INCL. FEE		\$	
PERMIT FEE		\$ 49.00	
TOTAL FEES		\$	
DWEELLING		REMARKS AND/OR VARIANCES	
		D 4931529 - final	