

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 13 2787	LOCATION 3410 Land Park Dr.			
DATE 4/3/39	PURPOSE New dwlg.			
ZONE 1 - 2nd	OWNER W. A. Mueller			
	ARCH'T. F. C. Mahenaw			
VAL. 7000	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	1857 ⁰¹
VENT SHAFTS	BOILER ROOMS	@ 132
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	1 ST Jump Form of <i>Amities</i>
4/28/39	2 ND Insp. Frame in place <i>OK</i> <i>W. Campbell</i>
7/5/39	3 RD Insp. INT & EXTH ^{LD} <i>OK</i> <i>W. Campbell</i>
7/12/39	4 TH Insp. Work with attached Garage Completed. Issued Final Inspection and Certificate of Occupancy.
7/12/39	COMPLETE AND O. K. <i>W. Campbell</i> INSPECTOR