

Q195-438-443

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$22.00

TYPE BUILDINGS *plans with 4203*

PERMIT NO. F-4331	LOCATION	6101 - South Land Park Dr.		A-3
DATE May 25-66	PURPOSE	Const. 2 retaining walls on R-1 lot		
ZONE R-1	OWNER	Mrs. Jean Watrous Kimberlin 920-23rd St		
	ARCH'T			
	CONTR	Assoc. Bldrs. Box 8521		
VAL. \$4,200.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM	<i>6.1.66</i>	<i>Fields</i>	J-2	
JOIST				
FRAME				
SHEET ROCK				
FINAL	<i>11/16/66</i>	<i>J. Barbato</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
5-26-66	Pt Area - Not ready	Count
5-31-66	Pt Area - Not ready	Count
6-3-66	OK 8' x 8' PB	75-5
4-6-66	OK all BB	Res
	Retaining Walls Checked	
	By Ken Veneola	
	COMPLETE AND OK	INSPECTOR

