

R139 71-3

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$19.00

TYPE BUILDINGS

| | | | | |
|-----------------------------|---------------------|---|-----------------|---------------------------|
| PERMIT NO. E-6437 | LOCATION | 1021 - West El Camino | | A-6 |
| DATE Mar. 6-64 | PURPOSE | Const. 1-room addition to dwelling | | |
| ZONE R-1 | OWNER | Ronald Green | | Same |
| | ARCH'T | 489-6535 | | |
| | CONT'R | O'Neal Homes 4625-Mulford Avenue | | |
| VAL. \$3,100. | STORIES 1 | ROOMS | APTS. | SIZE 364 sq.ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | 3-16-64 | Build | | |
| JOIST | | | | |
| FRAME | 3-31-64 | Plolo | | |
| SHEET ROCK | 4-8-64 | Plolo | | |
| FINAL | 6-12-64 | Perle | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|---|
| 3-13-64 | Pt not ready Hold |
| 3-31-64 | OK both Hold |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <div data-bbox="302 826 429 882" data-label="Text"> <p>COMPLETE AND OK</p> </div> <div data-bbox="1142 854 1274 882" data-label="Text"> <p>INSPECTOR</p> </div> |