

K-249 F-274

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS Double Fee

PERMIT NO. G-1930	LOCATION 2741 - San Luis Court A-2 (22)
DATE Nov-8-68	PURPOSE Repair pest damage to dwelling.
ZONE R-1	OWNER Mrs. Patterson Same
	ARCH'T 331-2633
	CONT'R Atox Termite Control 5831 - Rosebud Lane

VAL. \$500.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM				
JOIST				
FRAME				
SHEET				
ROCK				
FINAL	12.13.68	E. Lasser		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR