

78 - PRIMROSE WAY

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-29149	LOCATION 78 - 37th Way
DATE May 24-50	PURPOSE repair dwlg & garage
ZONE	OWNER Adriano
	ARCH'T.
	CONTR. Geo. W. Reed

VAL. 5600 ⁰⁰	STORIES 7	ROOMS 6	APTS.	SIZE
-------------------------	-----------	---------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	1120 ⁰⁰
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
8/1/50	Forms Insp. ————— J. E. Jones
9/17/50	Frame " ————— " " "
1-17-51	Final " ————— J. E. Jones
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>