

CITY OF SACRAMENTO

1231 I Street, Sacramento, CA 95814

Permit No: 0113538

Insp Area: 1

Thos Bros: 297 F4

Site Address: 714 22ND ST SAC

Parcel No: 003-0182-008

Sub-Type: RES

Housing (Y/N): N

CONTRACTOR

ZAP TERMITE
7233 26TH AV
RIO LINDA CA 95673

OWNER

RICHARD MELENDY
714 22ND ST
SACRAMENTO C A. 95841

ARCHITECT

Nature of Work: REPAIR SECOND STORY LANDING AND FIRST STORY SOFFIT BELLOW DUE TO WATER DAMAGE

CONSTRUCTION LENDING AGENCY : I hereby affirm under penalty of perjury that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097, Civ. C).

Lender's Name Lender's Address

LICENSED CONTRACTORS DECLARATION: I hereby affirm under penalty of perjury that I am licensed under provisions of Chapter 9 (commencing with section 7000) of Division 3 of the Business and Professions Code and my license is in full force and effect.

License Class License Number PR0149 Date 10/18/01 Contractor Signature Agent

OWNER-BUILDER DECLARATION: I hereby affirm under penalty of perjury that I am exempt from the contractors License Law for the following reason (Sec. 7031.5, Business and Professions Code; any city or county which requires a permit to construct, alter, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for such permit to file a signed statement that he or she is licensed pursuant to the provisions of the Contractors License Law (Chapter 9 (commencing with Section 7000) of Division 8 of the Business and Professions Code) or that he or she is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of not more than five hundred dollars (\$500.00);

I, as a owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business and Professional Code: The Contractors License Law does not apply to an owner of property who builds or improves thereon, and who does such work himself or herself or through his/her own employees, provided that such improvements are not intended or offered for sale. If, however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he/she did not build or improve for the purpose of sale.)

I, as owner of the property, am exclusively contracting with licensed contractors to construct the project (Sec. 7044, Business and Professions Code: The Contractors License Law does not apply to an owner of property who builds or improves thereon, and who contracts for such projects with a contractor(s) licensed pursuant to the Contractors License Law).

I am exempt under Sec. B & PC for this reason:

Date Owner Signature

IN ISSUING THIS BUILDING PERMIT, the applicant represents, and the city relies on the representation of the applicant, that the applicant verified all measurements and locations shown on the application or accompanying drawings and that the improvement does not violate any law or private agreement relating to permissible or prohibited locations for such improvements. This building permit does not authorize any illegal location of any improvement or the violation of any private agreement relating to location of improvements.

I certify that I have read this application and state that all information is correct. I agree to comply with all city and county ordinances and state laws relating to building construction and hereby authorize representative(s) of this city to enter upon the abovementioned property for inspection purposes.

Date 10/18/01 Applicant/Agent Signature Agent

WORKER'S COMPENSATION DECLARATION: I hereby affirm under penalty of perjury one of the following declarations:

I have and will maintain a certificate of consent to self-insure for workers' compensation as provided for by Section 3700 of the Labor Code, for the performance of work for which the permit is issued.

I have and will maintain workers' compensation insurance, as required by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued. My workers' compensation insurance carrier and policy number are:

Carrier STATE COMPENSATION INS FUND Policy Number 428-480 Exp Date 01/01/2002

(This section need not be completed if the permit is for \$100 or less) I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the workers' compensation laws of California and agree that if I should become subject to the workers' compensation provisions of Section 3700 of the Labor Code, I shall forthwith comply with those provisions.

Date 10/18/01 Applicant Signature Agent

WARNING: FAILURE TO SECURE WORKER'S COMPENSATION COVERAGE IS UNLAWFUL AND SHALL SUBJECT AN EMPLOYER TO CRIMINAL PENALTIES AND CIVIL FINES UP TO ONE HUNDRED THOUSAND DOLLARS (\$100,000) IN ADDITION TO THE COST OF COMPENSATION, DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST AND ATTORNEY'S FEE.

THIS PERMIT SHALL EXPIRE BY LIMITATION IF WORK IS NOT COMMENCED WITHIN 180 DAYS.



PLANNING & BUILDING DEPARTMENT
CITY OFFICES @ 13TH AND I STREETS

CITY OF SACRAMENTO
CALIFORNIA

PRESERVATION OFFICE
1231 I STREET, RM 200
SACRAMENTO, CA 95814
(916) 264-5957 Phone
(916) 264-5543 Fax

CERTIFICATE OF APPROPRIATENESS
for Minor Alterations, pursuant to Sections 15.124.280 and .285

Case Number: PB01-096 Date Filed: October 18, 2001

Action by the Preservation Director/Office on October 18, 2001

Final Action on the Certificate of Appropriateness by the Preservation Director/Office:

 APPROVED, or
 x APPROVED with the following conditions.

Address of Property: 714-22nd Street Assessor's Parcel Number: 003-0182-008

Resource Status/Classification: Contributing Structure in Boulevard Park Historic District

Project Description: The applicant proposes to replace the tile decking and repair any rotted framing members.

Findings of the Preservation Director/Office:

This Certificate of Appropriateness is issued pursuant to Sections 15.124.280 and .285 of the Preservation Ordinance, deeming this a minor project, and is determined by the Preservation Director to be consistent with the Secretary of Interior's Standards for the Treatment of Historic Properties, 1995.

Conditions:

1. Any stucco repair shall be done with matching stucco texture.

R. Marsh

Vincent Marsh, Preservation Director

10-18-01

Date

THE PRESERVATION DIRECTOR'S/OFFICE'S ACTION IS FINAL AND NOT SUBJECT TO APPEAL.
THIS IS NOT A PERMIT TO COMMENCE ANY WORK OR CHANGE OF OCCUPANCY UNLESS NO BUILDING
PERMIT IS REQUIRED. PERMITS FROM THE BUILDING DIVISION (AND ANY OTHER APPROPRIATE AGENCIES)
MUST BE SECURED BEFORE WORK IS STARTED OR OCCUPANCY IS CHANGED.

WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

This is an inspection report only -- not a Notice of Completion
ADDRESS OF PROPERTY INSPECTED

BUILDING NO.	STREET	CITY	ZIP	COUNTY CODE	DATE OF INSPECTION	NUMBER OF PAGES
714	22ND STREET	SACRAMENTO	95816	34	09/11/01	3

ZAP TERMITE & PEST CONTROL, INC.
7233 26th Street
Rio Linda, CA 95673
(800) 414-1515



Affix stamp here on Board copy only
A LICENSED PEST CONTROL OPERATOR IS AN EXPERT IN HIS/HER FIELD. ANY QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO HIM/HER.

REGISTRATION #	REPORT #	STAMP #	ESCROW #
PR 0149	78652A		

ORDERED BY: RICHARD MELENDY 714 22ND STREET SACRAMENTO CA 95816

REPORT SENT TO: _____


PROPERTY OWNER: RICHARD MELENDY 714 22ND STREET SACRAMENTO CA 95816

PARTY IN INTEREST: _____

GENERAL DESCRIPTION: <u>Limited Report</u>	IN ACCESSIBLE AREAS	NOT INSPECTED	FURTHER INSPECTION	SUBSTRATE ANTIMONITE	DRYWOOD TERMITES	FUNGUS GROWTH	OTHER WOOD PESTS	DAMPWOOD TERMITES	EARTHWOOD CONTACTS	FAULTY GRADE LEVELS	CEILING DAMBERS	EXPOSED VERTICALS	SHOW LEAKS	*Original Stamp #	Date
INSPECTION TAG POSTED: <u>Exterior decking</u>															
OTHER INSPECTION TAGS: _____															
1. SUBSTRUCTURE AREA <u>Limited report</u>		X	X												
2. STALL SHOWER <u>Limited report</u>		X	X												
3. FOUNDATIONS <u>Limited report</u>		X	X												
4. PORCHES -- STEPS <u>Limited report</u>		X	X												
5. VENTILATION <u>Limited report</u>		X	X												
6. ABUTMENTS <u>Limited report</u>		X	X												
7. ATTIC SPACES <u>Limited report</u>		X	X												
8. GARAGES <u>Limited report</u>		X	X												
9. DECKS -- PATIOS <u>Limited report</u>		X	X												
10. OTHER -- INTERIOR <u>Limited report</u>		X	X												
11. OTHER -- EXTERIOR <u>Limited report</u>			X	X			X								

DIAGRAM AND EXPLANATION OF FINDINGS (This report is limited to structure or structures shown on diagram)

NOTE: DIAGRAM NOT TO SCALE & FINDINGS IN APPROX. LOCATIONS



Inspected by Ron Pruter

License No. FR9064

Signature _____

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 263-2533, or (800) 737-8188. You are entitled to obtain copies of all reports and completion notices on this property filed with the Board during the preceding two years upon payment of a \$2.00 search fee to: The Structural Pest Control Board, 1418 Howe Ave., Ste. 18, Sacramento, California 95825-3204.

714	22ND STREET	SACRAMENTO
BLDG. NO.	STREET	CITY
	09/11/2001	78652A
STAMP NO.	DATE OF INSPECTION	CO. REPORT NO.

This is a limited inspection to the 2nd story landing and the base of the exposed 4x4 support post.

ZAP PEST CONTROL recommends a complete inspection of the property.

During the course of repairs, any damage or infestation found in areas not visible during the inspection will be reported on a supplemental report with an estimate for repairs.

A Wood Destroying Pest and Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest and Organisms Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest and Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either the inspector or the company issuing a Wood Destroying Pest and Organism Inspection Report.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of the hollow walls, spaces between floors, areas concealed by carpeting, built-in appliances, or cabinet work. Infestations or infections may be active in these areas without visible and accessible evidence. Areas that were not inspected are noted in the report. If you desire information about areas that were not inspected, a further inspection may be performed at additional cost.

In accordance with Section 1990 of the Structural Pest Control Act, the following areas are considered inaccessible:

Interior of hollow walls
Spaces between the floors and ceiling below

No painting of any repaired areas is included in any bids given.

NOTICE: REPORTS ON THIS STRUCTURE PREPARED BY VARIOUS REGISTERED COMPANIES SHOULD LIST THE SAME FINDINGS (I.E. TERMITE INFESTATIONS, TERMITE DAMAGE, FUNGUS DAMAGE, ETC). HOWEVER, RECOMMENDATIONS TO CORRECT THESE FINDINGS MAY VARY FROM COMPANY TO COMPANY. YOU HAVE A RIGHT TO SEEK A SECOND OPINION FROM ANOTHER COMPANY.

OTHER - EXTERIORS:

Item 11A: Water stains were found on the soffit below the 2nd story tile landing, at the request of the home owner, Mr. Melendy. Remove the tile landing and plywood subfloor. Install a new plywood subfloor and a hot mop membrane. Install new tile set in montor. Reinstall handrail.

During the course of repairs, any damage or infestation found in areas not visible during the inspection will be reported on a supplemental report with an estimate for repairs.

Item 11B: Evidence of subterranean termite damage was found to the base of the 4x4 support post, further inspection is recommended in this area. Remove the stucco at this area for further inspection.

NOTE: Bid is for further inspection only. A supplemental report will be issued after area is open.

714	22ND STREET	SACRAMENTO
BLDG. NO.	STREET	CITY
	09/11/2001	78652A
STAMP NO.	DATE OF INSPECTION	CO. REPORT NO.

OTHER - EXTERIORS:

NOTE: For cost of repairs, please refer to a separate document.

NOTE: The bid in Item #11A does not include cost of tile and grout, owner to supply.

ZAP TERMITE & PEST CONTROL, INC.

7233 26th Street
Rio Linda, CA 95673
(800) 414-1515



WORK AUTHORIZATION CONTRACT

Address of Property: 714 22ND STREET SACRAMENTO, CA. 95816
Inspection Date: 09/11/2001
Termite Report #: 78652A
State Stamp #:
Title Co. & Escrow #:

ITEM BREAKDOWN

11A: \$ 4850.00 11B: \$ 200.00

We Authorize the Following Items to be Performed.

Proposed Cost: \$ 5050.00
Inspection Fee: _____
Total: \$ 5050.00

CUSTOMER INFORMATION

The prices quoted above are subject to ZAP performing all items. In the event ZAP is requested to perform a portion of the repairs the price is subject to revision. Minimum job cost is \$200.00

The total amount of this contract is due and payable upon completion of work unless specified otherwise in the body of this contract. Should an escrow be involved and the undersigned requests that the amount of this contract be billed to an existing escrow the undersigned hereby agrees that the escrow holder will be provided with instructions that all monies due ZAP TERMITE & PEST CONTROL IS TO BE PAID THROUGH THE PROCEEDS AT CLOSE OF SUCH ESCROW OR IN THIRTY DAYS, WHICHEVER OCCURS FIRST. IF ESCROW DOES NOT CLOSE WITHIN THIRTY DAYS, ZAP TERMITE & PEST CONTROL WILL EXPECT PAYMENT FROM THE PARTY WHO ORDERED THE WORK. SHOULD AT ANY TIME AN EXISTING ESCROW BE CANCELLED ALL MONIES OWED ZAP TERMITE & PEST CONTROL BECOMES IMMEDIATELY DUE AND PAYABLE.

ZAP TERMITE & PEST CONTROL agrees to use reasonable care in the performance of all work but assumes no responsibility for damage to any hidden electric, plumbing, or heating pipes, wiring or other facilities or appurtenances, or to any shrubs, plants or other life. If work includes repairs to a shower, unless otherwise specified to the contrary, ZAP TERMITE & PEST CONTROL will not be responsible for any damage to the tile or plaster eight inches above the floor level of such shower. No painting is included in any estimate unless specified in the body of this contract.

THIS CONTRACT PROVIDES FOR THE RETREATMENT OF INFESTED AREAS OF THE COVERED STRUCTURE IN THE EVENT THAT THE ORIGINALLY TREATED PEST REINFEST THE COVERED STRUCTURE, BUT THIS CONTRACT DOES NOT PROVIDE FOR THE REPAIR OF DAMAGE CAUSED BY THAT SAME ORIGINALLY TREATED PEST. SUBTERRANEAN TERMITE TREATING IS WARRANTED FOR ONE YEAR. WOOD DESTROYING BEETLE AND DRYWOOD TERMITE TREATMENTS, INCLUDING FUMIGATION, ARE WARRANTED FOR ONE YEAR. OTHER REPAIRS ARE WARRANTED FOR ONE YEAR, EXCEPT PLUMBING AND CAULKING REPAIRS. PLUMBING AND CAULKING REPAIRS ARE WARRANTED FOR THIRTY DAYS. SHOULD REMOVAL OF STRUCTURAL ITEMS OR REPAIRS, NOT LISTED IN THIS AGREEMENT, REQUIRE REPAIR OR REMOVAL, THE HOMEOWNER AGREES TO PREFORM NEEDED REPAIRS OR REMOVAL SEPERATE OF THIS AGREEMENT.

All terms of agreement between the parties are contained in this contract and no other terms or statements shall be binding upon the parties. In case of non-payment the undersigned hereby agrees to pay reasonable attorneys' fees and costs of collection whether suit be filed or not.

NOTICE UNDER MECHANIC'S LIEN LAW : (California Civil Code, Section 3110 ET SEQ). Any contractor, sub-contractor, laborer, supplier or any other person who helps to improve your property but is not paid for his work or supplies has a right to enforce a claim against your property. This means that after a court hearing your property could be sold by a court official and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your own contractor in full, if the sub-contractor or laborer or supplier remains unpaid. This paragraph constitutes pre-lien notice under the Mechanic's Lien Law. Section 3097.
NOTE: Inspection fee is billed separately above any work costs.

In the event that legal action is necessary to enforce the terms of this agreement by any party hereto, attorney's fees may be awarded to the prevailing party. In no event are monies to be held in escrow past the close of escrow without prior consent by ZAP TERMITE & PEST CONTROL. Interest will be charged at 1 1/2% per month after 30 days.

I Have Read This Contract And The Termite Report It Refers To.
SIGNED WORK AUTHORIZATION CONTRACT MUST BE RECEIVED BEFORE WORK WILL BE SCHEDULED.
I have read and understand the terms of this work authorization contract and hereby agree to all terms thereof.

APPROVED AND READ BY: _____ DATE _____
RICHARD MELENDY

ACCEPTED FOR: _____ DATE 9/12/01
ZAP TERMITE & PEST CONTROL, INC.

15755
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

This is an inspection report only -- not a Notice of Completion
ADDRESS OF PROPERTY INSPECTED

BUILDING NO. 714	STREET 22ND STREET	CITY SACRAMENTO	ZIP 95816	COUNTY CODE 34	DATE OF INSPECTION 10/24/01	NUMBER OF PAGES 3
---------------------	-----------------------	--------------------	--------------	-------------------	--------------------------------	----------------------

ZAP TERMITE & PEST CONTROL, INC.

7233 26th Street
Rio Linda, CA 95673
(800) 414-1515



Affix stamp here on Board copy only
A LICENSED PEST CONTROL OPERATOR IS AN EXPERT IN HIS/HER FIELD. ANY QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO HIM/HER.

REGISTRATION # PR 0149	REPORT # 78652B	STAMP #	ESCROW #
---------------------------	--------------------	---------	----------

ORDERED BY: RICHARD MELENDY 714 22ND STREET SACRAMENTO CA 95816

REPORT SENT TO: _____

PROPERTY OWNER: RICHARD MELENDY 714 22ND STREET SACRAMENTO CA 95816

PARTY IN INTEREST: _____


ORIGINAL REPORT LIMITED REPORT SUPPLEMENTAL REPORT * REINSPECTION REPORT * *Original Stamp # _____ Date 09/11/01

GENERAL DESCRIPTION: <u>Supplemental Report</u>	INACCESSIBLE AREAS	NOT INSPECTED	FURTHER INSPECTION	SUBSTRANZAN TERMITES	DRYWOOD TERMITES	FUNGUS OR ROT	OTHER WOOD PESTS	DAMPWOOD TERMITES	EARTH WOOD CONTACTS	FAULTY SEWER LINES	CELLULOSE EMBERS	EXCESSIVE MOISTURE	SHOWERS
INSPECTION TAG POSTED: <u>Exterior decking</u>													
OTHER INSPECTION TAGS: _____													
1. SUBSTRUCTURE AREA	Supplemental report												
2. STALL SHOWER	Supplemental report												
3. FOUNDATIONS	Supplemental report												
4. PORCHES -- STEPS	Supplemental report												
5. VENTILATION	Supplemental report												
6. ABUTMENTS	Supplemental report												
7. ATTIC SPACES	Supplemental report												
8. GARAGES	Supplemental report												
9. DECKS -- PATIOS	Supplemental report												
10. OTHER -- INTERIOR	Supplemental report												
11. OTHER -- EXTERIOR	Supplemental report												

DIAGRAM AND EXPLANATION OF FINDINGS (This report is limited to structure or structures shown on diagram)

NOTE: Diagram not to scale & findings in approx. locations

\$15,755⁰⁰ value was added to # 0113538 for items 11C and 11D



Inspected by Ron Pruter License No. FR9064 Signature [Signature]

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 263-2533, or (800) 737-8188. You are entitled to obtain copies of all reports and completion notices on this property filed with the Board during the preceding two years upon payment of a \$2.00 search fee to: The Structural Pest Control Board, 1418 Howe Ave., Ste. 18, Sacramento, California 95825-3204.

714	22ND STREET	SACRAMENTO
BLDG. NO.	STREET	CITY
	10/24/2001	78652B
STAMP NO.	DATE OF INSPECTION	CO. REPORT NO.

This is a supplemental report to Report # 78652A, Dated 9-11-01, and is issued for the purpose of reporting conditions found in previously inaccessible or concealed areas, since made accessible and inspected.

OTHER EXTERIORS:

Item 11C: During the course of the repairs outlined in 11A, additional fungus damage was found to the stucco partition wall at the left rear portion of the structure. Remove the stucco exposing fungus damaged wall sheathing and frame. Remove damaged frame and wall sheathing and replace with new material. Restucco disturbed area to a responsible match. An exact match of existing stucco is not guaranteed. NOTE: During the course of the repairs, the damage was found to extend past the area designated by this report. The homeowner, Richard Melendy, has requested no repairs be performed past the designated area. Install new window sash.

No painting of any repaired areas is included in any bids given.

During the course of repairs, any damage or infestation found in areas not visible during the inspection will be reported on a supplemental report with an estimate for repairs.

NOTE: During the course of repairs if it becomes necessary to remove electrical panels, junction boxes and/or switches, such will be performed by the homeowner, at his cost. Bid does not include any electrical repairs.

Item 11D: As outlined in the original report, item 11B, further inspection was performed at the base of the 4x4 support post. Evidence of subterranean termites and subterranean termite damage was noted to the lower framing. Remove the stucco exposing lower framing. Remove and replace damaged framing with new material. Restucco disturbed area to a responsible match. An exact match of existing is not guaranteed.

Item 11E: For the control of subterranean termites, drill holes adjacent to the 4x4 support post. Chemically treat soil and seal drill holes. Guarantee is limited to treated areas only.

714	22ND STREET	SACRAMENTO
BLDG. NO.	STREET	CITY
	10/24/2001	78652B
STAMP NO.	DATE OF INSPECTION	CO. REPORT NO.

OCCUPANTS CHEMICAL NOTICE

ZAP TERMITE & PEST CONTROL will use pesticide chemical(s) specified below for the control of wood destroying pests or organisms in locations identified in the Structural Pest Control report as indicated above.

(1) The pest(s) to be controlled:

- SUBTERRANEAN TERMITES
- FUNGUS or DRY ROT
- BEETLES
- DRY-WOOD TERMITES
- OTHER _____

(2) The pesticide(s) proposed to be used and the active ingredient(s).

- A. DRAGNET: Active ingredients: Permethrin
- B. TIM-BOR: Active ingredients: Disodium Octaborate Terahydrate
- C. METHYL BROMIDE 99.5: Active ingredient: Methyl Bromide
- D. VIKANE: Active ingredients: Sulfuryl Fluoride
- E. CHLOROPICRIN: Active ingredients: Chloropicrin
- F. PREVAIL FT: Active Ingredients: Cypermethrin
- G. PREMISE 75: Active ingredients: Imidacloprid
- H. TERMIDOR SC: Active ingredient: Fipronil
- I. OTHER: _____

(3) "State Law requires that you be given the following information: CAUTION-PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Operators are licensed and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Food and Agriculture and the United States Environmental Protection Agency. Registration is granted when the State finds that based on existing scientific evidence there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, so exposure should be minimized.

"If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest operator immediately. (This statement shall be modified to include any other symptoms of over exposure which are not typical of influenza.)" For further information, contact any of the following:

POISON CONTROL CENTER: (800) 342-9293

Structural Pest Control
1418 Howe Avenue, Ste. 18, Sacramento, CA 95825 (800) 737-1418

COUNTY	COUNTY HEALTH DEPT.	COUNTY AGRICULTURE DEPT.
Sacramento	(916) 366-2176	(916) 875-6603
Yolo	(530) 666-8649	(530) 666-8141
El Dorado	(530) 626-2131	(530) 621-5520
Placer	(530) 889-7141	(530) 889-7372
Yuba	(530) 741-6484	(530) 741-6366
Sutter	(530) 671-1140	(530) 741-7500
Nevada	(530) 265-1450	(530) 273-2648
Solano	(707) 421-6770	(707) 421-7465

Persons with respiratory or allergic conditions, or others who may be concerned about their health relative to this chemical treatment, should contact their physician concerning occupancy during and after chemical treatment prior to signing this NOTICE.

NO CHEMICAL APPLICATION WILL BE PERFORMED UNTIL SUCH TIME THAT THIS NOTICE IS RETURNED. HAVING READ THE INSTRUCTIONS, I, THE UNDERSIGNED, WILL ACCEPT RESPONSIBILITY FOR ALL THE AFOREMENTIONED.

OWNER / OCCUPANT	DATE	OWNER / OCCUPANT	DATE
------------------	------	------------------	------