

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. A-1364	LOCATION REMODEL JOB. 220 - P Street			
DATE 1/30/34	PURPOSE Raised Bldg 4' and install Church on 1st Floor & Repairs			
ZONE Gen. Com.	OWNER Nicherson Church			
	ARCH'T Japanese Bldg. Co.			
	CONT-R			
VAL. 1000 00	STORIES 2	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
1/30/34	Made Partial Skeleton of structure to be made + ...
	... New + joint built ... A.W. Campbell
2/6/34	2nd story (PARTIAL FRAME) A.W. Campbell
2/8/34	2nd " " " " A.W. Campbell
7/15/34	2nd " " " " A.W. Campbell
2/16/34	2nd " " Steel Beams & Posts in place A.W. Campbell
4/10/34	3rd INSPI. INT LATH Metal on Ceiling in Wall & ... A.W. Campbell
4/2/34	4th ...
4/4/34	COMPLETE AND O.K. INSPECTOR