

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>Perch</i>	LOCATION <i>568 Smith</i>		
DATE	PURPOSE <i>in Rep Garage</i>	ROOMS	APTS.
ISSUE SF ZONE SACRAMENTO BUILDING DEPT.	OWNER <i>Mrs A Williams</i>	PHONE	
	ARCH'T <i>DT</i>		
	CONT'R <i>Or</i>		
VAL. <i>100 -</i>	STORIES	SIZE	

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
9/14/27	1 st Flr. Ceiling Floor in Garage
9/14/27	2 nd Flr. Frame up.
	Noticed Owner that inasmuch as permit
	for garage was taken out under S.C.
	building regulations it would be O.K.
	to put Cor. Iron on Wall on line with
	other pipe & conduct water on one lot.
	W. D. Dumble
	<p>COMPLETED AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>