

*Q150 466*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

PERMIT NO. S-4411		LOCATION 2245 - Florin Road		A-4	
DATE Oct 29-65		PURPOSE Const. sign Class A			
ZONE C-2		OWNER Grand Plaza Dept. Store same			
		ARCH'T			
		CONTR Ad-Art, Inc. Box 2308		922-5671	
VAL. \$500.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM					
JOIST					
FRAME					
SHEET					
ROCK					
FINAL	<i>11-18-65</i>	<i>[Signature]</i>		<i>ent</i>	

1. This form is to be filled out by the building inspector only. It is not to be filled out by the contractor or the owner. 2. The building inspector should check the building for compliance with the building code and the fire code. 3. The building inspector should check the building for compliance with the health and safety code. 4. The building inspector should check the building for compliance with the electrical code. 5. The building inspector should check the building for compliance with the plumbing code. 6. The building inspector should check the building for compliance with the mechanical code. 7. The building inspector should check the building for compliance with the fire code. 8. The building inspector should check the building for compliance with the health and safety code. 9. The building inspector should check the building for compliance with the electrical code. 10. The building inspector should check the building for compliance with the plumbing code. 11. The building inspector should check the building for compliance with the mechanical code.

DATE	SPECIAL CONDITIONS OF WORK -- REMARKS
	<p data-bbox="279 829 397 881"><b>COMPLETE AND OK</b></p> <p data-bbox="1085 857 1204 881"><b>INSPECTOR</b></p>