



DATE	CONDITION OF WORK--REMARKS
6/11/27	1 <sup>ST</sup> / MSP. Concrete Floor in Garage. O.K. L.V. Campbell will build back wall on lower side.
	COMPLETED AND O. K. <span style="float: right;">Inspector</span>