

R.388E

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$12.00

TYPE BUILDINGS

| | | | | | |
|-------------|---------------------|-------------------------------|-------|-----------------|---------------|
| PERMIT NO. | | LOCATION | | | |
| H-6860 | | 3501 - Sheldon Street A-6 | | | |
| DATE | | PURPOSE | | | |
| May 9-72 | | Reroof dwelling | | | |
| ZONE | | OWNER | | | |
| R-1 | | David H. Elder | | | |
| | | ARCH'T | | | |
| | | CONT'R | | | |
| | | Jack Snyder P.O. Box 693 W.S. | | | |
| VAL. \$800. | | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | | 371 6876 |
| JOIST | | | | | |
| FRAME | | | | | |
| SHEET | | | | | |
| ROCK | | | | | |
| FINAL | <i>P.F. 8-14-73</i> | <i>Dana Fuller</i> | | | |

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |