

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-4397</i>	LOCATION <i>4029 - Miller Way</i>			
DATE <i>12/5/39</i>	PURPOSE <i>New duplex</i>			
ZONE <i>2 fam</i>	OWNER <i>D. A. Lindsay</i>			
	ARCH'T.			
	CONT'R. <i>Universal Const. Co.</i>			
VAL. <i>5000.00</i>	STORIES <i>1</i>	ROOMS <i>9</i>	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS			BOILER ROOMS	<i>1570 sq ft</i>
OWNER'S INSPECTOR			SPRINKLER SYSTEM	<i>@ 3'</i>
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

..DATE.	CONDITION OF WORK-REMARKS	
1-15-39	15' Jump	Form on <u>Right</u>
1-26-40	2 "	Frame " <u>Right</u>
	<p style="text-align: center;">COMPLETE AND O. K.</p>	

33-13,60

$$\begin{array}{r} 00 \\ 00 \\ 00 \\ \hline 00 \end{array}$$

$$\begin{array}{r} 00 \\ 00 \\ 00 \\ \hline 00 \end{array}$$

$$\begin{array}{r} 0.0 \\ 0.5 \\ 0.5 \\ \hline 0.5 \end{array}$$

$$\begin{array}{r} 0.1 \\ 0.1 \\ 0.1 \\ \hline 0.5 \end{array}$$

$$\begin{array}{r} 0.6 \\ 0.6 \\ 0.6 \\ \hline 0.6 \end{array}$$

INSPECTOR