

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-6857</i>	LOCATION <i>1527 — 7th St.</i>
DATE <i>8/24/37</i>	PURPOSE <i>Rebuild porch appears to say</i>
ZONE <i>—</i>	OWNER <i>Mc Clatchy Realty Co.</i>
	ARCH'T.
	CONT'R. <i>J. F. Reynolds</i>

VAL. <i>300</i>	STORIES	ROOMS	APTS.	SIZE
-----------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
	<p>Made preliminary drops R. front porch & steps badly damaged by dry rot & Termites. Contn going to tear down and rebuild new front porch & steps.</p>
8/28/37	2 nd INSP. Frame O. K. A. W. Campbell
9/13/37	3 rd INSP. Ext. Lath In Place. ^{OR} A. W. Campbell
9/20/37	4 th INSP. Rebuilt porch & steps Completed
9/20/37	<p>COMPLETE AND O. K. <i>A. W. Campbell</i> INSPECTOR</p>