

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10384</i>	LOCATION <i>187 - San Antonio Way</i>			
DATE <i>5/22/42</i>	PURPOSE <i>Erect new dwg. 4 gm</i>			
ZONE <i>-</i>	OWNER <i>Mary E. Phillips</i>			
	ARCH'T. <i>W. B. Phillips</i>			
	CONTR. <i>W. B. Phillips</i>			
VAL. <i>3000</i>	STORIES <i>-</i>	ROOMS <i>4</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>	
VENT SHAFTS		BOILER ROOMS	<i>785 sq ft</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS	
	151	Lump Formed at Quarter
7/1/42	2 "	Frame at Quarter
7/3 "	2 "	Lash to End of Quarter
8/27 "	4 "	Towed at Quarter
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>	