

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA																	
PROPERTY PARCEL NO.		JOB ADDRESS															
		2512 Casa Linda Drive															
LEGAL DESCRIPTION		Lot 19 Meadowview Terrace															
TITLE AND NAME		1/3															
GEN. CONTR.		Owner															
ELEC. CONTR.																	
PLBG. CONTR.																	
MECH. CONTR.																	
ARCH. ENGR.																	
OWNER		Alegn Pacific Co															
CONST. LOAN LENDER																	
ISSUED BY		MICROFILM RECORD															
ISSUANCE DATE		10-3-58		REEL NO. 47		FRAME NO. 492		TO		493		REEL NO.		FRAME NO. 11041022			
VALUATION		\$10,200		INSPECTION RECORD		REEL NO.		FRAME NO.		TO		REEL NO.		FRAME NO.			
R.U.F. FEE		\$		JOB FILE		REEL NO.		FRAME NO.		TO		REEL NO.		FRAME NO.			
S.M.I. FEE		\$		PLANCK. FEE		REEL NO.		FRAME NO.		TO		REEL NO.		FRAME NO.			
SEWER INCL. FEE		\$		PERMIT FEE		REEL NO.		FRAME NO.		TO		REEL NO.		FRAME NO.			
TOTAL FEES		\$		\$31.00		REEL NO.		FRAME NO.		TO		REEL NO.		FRAME NO.			
REMARKS AND/OR VARIANCES		Const dwelling and att. garage Plan;															
PERMIT NO. S.P.		C-9971															
NATURE OF WORK:		Const dwelling and att. garage Plan;															
SIDE YARDS																	
REAR YARDS																	
SET BACK REQ.																	
USE ZONE		I															
PARK'G REQ.																	
SPACES																	
TREES RMVD.																	
EXISTING BLDG'S SAME LOT																	
HOW USED																	
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT		NO. OF STORIES		ROOF CONSTR.		AREA 1st FLOOR		TOTAL AREA		C.S.D.		C.I. CASE	
DATE		DATE		DATE		DATE		DATE		DATE		DATE		DATE		DATE	
ISSUED BY		ISSUED BY		ISSUED BY		ISSUED BY		ISSUED BY		ISSUED BY		ISSUED BY		ISSUED BY		ISSUED BY	
CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY		CERTIFICATE OF OCCUPANCY	
MECHANICAL BY		MECHANICAL BY		MECHANICAL BY		MECHANICAL BY		MECHANICAL BY		MECHANICAL BY		MECHANICAL BY		MECHANICAL BY		MECHANICAL BY	
PLUMBING BY		PLUMBING BY		PLUMBING BY		PLUMBING BY		PLUMBING BY		PLUMBING BY		PLUMBING BY		PLUMBING BY		PLUMBING BY	
ELECTRICAL BY		ELECTRICAL BY		ELECTRICAL BY		ELECTRICAL BY		ELECTRICAL BY		ELECTRICAL BY		ELECTRICAL BY		ELECTRICAL BY		ELECTRICAL BY	
BUILDING BY		BUILDING BY		BUILDING BY		BUILDING BY		BUILDING BY		BUILDING BY		BUILDING BY		BUILDING BY		BUILDING BY	
DATE		DATE		DATE		DATE		DATE		DATE		DATE		DATE		DATE	
2-20-59		2-20-59		2-20-59		2-20-59		2-20-59		2-20-59		2-20-59		2-20-59		2-20-59	

2512 Casa Linda Dr. 5-0