

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$3.00

**TYPE BUILDINGS**

R-75  
FHCO

<b>PERMIT NO.</b> D-6826	<b>LOCATION</b> 3220 Sacto. Blvd. A-1
<b>DATE</b> Sep 22, 60	<b>PURPOSE</b> Repair auto damage to store Bldg.
<b>ZONE</b>	<b>OWNER</b> J. Huey
	<b>ARCH'T</b>
	<b>CONT'R</b> Chas Vanina 2022 Capitol Ave GI 25624

<b>VAL.</b> \$500	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
-------------------	----------------	--------------	--------------	-------------

<b>INSP.</b>	<b>DATE</b>	<b>INSPECTOR</b>
<b>FORM</b>		
<b>JOIST</b>		
<b>FRAME</b>		
<b>LATH</b>		
<b>FINAL</b>	9-23-60	Bachato

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>