

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-4057</i>	LOCATION <i>5301 - 5 Street</i>			
DATE <i>10/18/39</i>	PURPOSE <i>Erect new double garage</i>			
ZONE <i>1</i>	OWNER <i>Geo Froyer</i>			
	ARCH'T. <i>Fred Miller</i>			
	CONTR. <i>Fred Miller</i>			
VAL. <i>2000<sup>00</sup></i>	STORIES	ROOMS	APX	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 724<sup>01</sup> @ 30-</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS	
10/25-30/31	1	Imp. Form. & P. 10
11-9-39	2	Form. " P. 10
11-10-39	3	Sub. Imp. & P. 10
1-26-40	4	Finished by P. 10

COMPLETE  
AND O. K.

INSPECTOR