

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5817</i>	LOCATION <i>940 - Robertson wa</i>			
DATE <i>6/19/40</i>	PURPOSE <i>Build a double gar</i>			
ZONE <i>-</i>	OWNER <i>W. E. Burrows</i>			
	ARCH'T. <i>J. B. Galland</i>			
	CONTR. <i>J. B. Galland</i>			
VAL. <i>4000</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS	<i>1123 P'</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 342</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
6/28/40	1 ST /NSP. Frame in place ^{OK} A.W. Campbell
7/18-40	2 " Frame OK ^{OK} Quinter
7/24/40	3 " Lath OK ^{OK} Quinter
10/4/40	4 TH /NSP. Dwg + Garage Completed ^{OK} A.W. Campbell
10/4/40	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR