

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 4816</i>	LOCATION <i>4008 - Miller Way</i>
DATE <i>2/16/45</i>	PURPOSE <i>Erect new dwls & apt</i>
ZONE	OWNER <i>H. O. Beyersdorf</i>
	ARCH'T.
	CONTR. <i>Universal Const. Co.</i>

VAL. <i>3000</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area 860 sq ft @ 350</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
BATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS.
2/19-40	15' Drop Formwork on Piles
3/25-40	2 " Frame on Piles
4-10-40	3 " South Side of Piles
	<p data-bbox="288 854 423 896">COMPLETE AND O. K.</p> <p data-bbox="1135 865 1276 890">INSPECTOR</p>