

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 4816</i>	LOCATION <i>4008 - Miller Way</i>
DATE <i>2/16/45</i>	PURPOSE <i>Erect new dwls & apt</i>
ZONE	OWNER <i>H. O. Beyersdorf</i>
	ARCH'T.
	CONTR. <i>Universal Const. Co.</i>

VAL. <i>3000</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area 860 sq ft @ 350</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
BATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS.	
2/19-40	15'	Frames of Pumps
3/25-40	2 "	Frames of Pumps
4-10-40	3 "	South End of Pumps
	COMPLETE AND O. K.	INSPECTOR