

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5545-</i>	LOCATION <i>110 - Robertson Way</i>
DATE <i>1/18/37</i>	PURPOSE <i>Erect new dwlg.</i>
ZONE	OWNER <i>Mrs H. P. Andrews</i>
	ARCH'T.
	CON'T'R. <i>A. Bruce Asbery</i>

VAL. <i>5000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>\$5000</i>
VENT SHAFTS	BOILER ROOMS	<i>area</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>1275</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
1/21/37	1 <sup>ST</sup> HSP. Forms in place Indus Dwg. <sup>OK</sup> A.W. Campbell
4/9/37	2 <sup>ND</sup> HSP. Forme . . . <sup>OK</sup> A.W. Campbell
7/22/37	3 <sup>RD</sup> HSP. INT. & EXTLATH <sup>OK</sup> A.W. Campbell
4/26/37	4 <sup>TH</sup> HSP Dwg with Garage attached to same - Completed. O.K. A.W. Campbell
4/26/37	Issued Final Insp & Cert. parts of Occupancy Struct. Check up.
4/26/37	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR