

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3563</i>	LOCATION <i>1331 Robertson - 7958 - 14th St.</i>
DATE <i>8/3/39</i>	PURPOSE <i>Erect new duplx</i>
ZONE <i>2-Ham</i>	OWNER <i>Frank J. Hooper</i>
VAL. <i>7900⁰⁰</i>	ARCH'T. <i>A. Bruce Osburn</i>
STORIES <i>1</i>	ROOMS <i>9</i>
APTS. <i>1</i>	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS <i>Area</i>
VENT SHAFTS	BOILER ROOMS <i>700'</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM <i>@ 32</i>
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK-REMARKS
8.8.39	1 st Insp Forms OK <i>Director</i>
9/11/39	2 nd Insp. Frame in place ^{OK} <i>MW Campbell</i>
9/13/39	3 rd Insp. Int & Ext ^{OK} <i>MW Campbell</i>
11/9/39	4 th Insp Duplex Dials & Gauge Completed
	Issued Final Insp. & Cert. of Occy
	Shop cleaned up OK
11/9/39	<div style="display: flex; justify-content: space-between; align-items: center;"> <div data-bbox="288 865 414 906">COMPLETE AND O. K.</div> <div data-bbox="429 839 1041 927"><i>M. W. Campbell</i></div> <div data-bbox="1128 880 1266 906">INSPECTOR</div> </div>