

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
5837 Carlsson Drive		1-S		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
5837 Carlsson Drive					
TITLE AND NAME					
1/c					
ADDRESS					
CITY LIC. NO.					
TEL. NO.					
ELECTRICAL BY					
DATE					
GEN. CONTR.					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
CONST. LOAN LENDER					
CERTIFICATE OF OCCUPANCY					
ISSUED BY					
DATE					
BLDG. WIDTH					
BLDG. LENGTH					
TOTAL HEIGHT					
NO. OF STORIES					
ROOF CONSTR.					
AREA 1st FLOOR					
TOTAL AREA					
C.S.D.					
C.I. CASE					
CENTRUS TRCT. NO.					
SIDE YARDS					
REAR YARDS					
SET BACK REQ.					
USE ZONE					
PARK'G REQ.					
SPACES					
TREES RMVD.					
EXISTING BLDG'S SAME LOT					
HOW USED					
NATURE OF WORK:-					
PERMIT NO. S.P.					
ISSUED BY					
MICROFILM RECORD					
ISSUANCE DATE					
PLANS AND APPLICATION					
REEL NO.					
FRAME NO.-					
TO					
INSPECTION RECORD					
REEL NO.					
FRAME NO.-					
TO					
JOB FILE					
REEL NO.					
FRAME NO.-					
TO					
S.M.I. FEE					
\$					
PLAN CK. FEE					
\$					
SEWER INCL. FEE					
\$					
PERMIT FEE					
\$					
REMARKS AND/OR VARIANCES					
Sidewalk Plaza					
TOTAL FEES					
\$					