

ISSUED

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

JUL - 5 1930

TYPE VII BUILDINGS

PERMANENT LOCATION
BUILDING DIVISION

3200 San Carlos Way

6531

PURPOSE

ROOMS

APTS.

Re-Roof Duct w/ins Comp Shingles

OWNER

PHONE

F. M. BURNS, 3200 San Carlos Way

DATE

July 5th
1930

ARCH'T

ZONE

2-Family

CONTR

STAR ROOF CORP. 1715-5TH ST

VAL.

294[±]

STORIES

1

SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX WALL	Jolts						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
7/8-30	Inspection of <i>R. H. Rutter</i>
	COMPLETED AND O.K. INSPECTOR