

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
4/15/24	\$50.00	7580	Frame dwelling	J. Pesce Owner			
9/18/28	\$200.00	3375	add room	L. Dean Owner			
12-18-80	B \$4135.	H-9553	Dry Rot Repair	R. Jencke Safe Guard Co.	7846 FO. BI.	Jimmy	2-20-81
1-5-81	Bldg. \$501	H-9885 \$30.	Reroof	B. Bicker	Pioneer Roofing	NO FINAL INSPECTION	
4-27-81	P \$600.00	I-1355 \$30.00	Replace sewer GOLF 4"	Blickes	Frank Sewer Ser.		5/5/81
			Jim sewer.	2461 Castro Way	3010 Marysville Blvd		

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
7580	H 489F516 - comp	H-9885	H 773F333		
3375	H 489F516 - comp	H-9553	H 984 257		
H-9553	D 552F109				
H-9885	K 665F164				
H-9553	R 665F331-338				
I-1355	R 670F466				
1355	R X 9F146				