

**RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA**

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA		FINAL INSPECTIONS	
		5330 H Street					1			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
TITLE AND NAME		1/C	ADDRESS			ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
GEN. CONTR.									PLUMBING BY	DATE
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.									CERTIFICATE OF OCCUPANCY	
MECH. CONTR.									ISSUED BY	DATE
ARCH. ENGR.										
OWNER										
CONST. LOAN LENDER										
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
							CENSUS TRCT. NO.			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

**NATURE OF WORK:-**

PERMIT NO. S.P. -		<b>MICROFILM RECORD</b>			
ISSUED BY					
ISSUANCE DATE	PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO	
VALUATION \$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO	
R.D.F. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO	
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$	<b>REMARKS AND/OR VARIANCES</b>				
\$					
\$					
TOTAL FEES \$					

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
7/19/76	B \$ 1,100.00	D-5518 \$ 20	25 sqa roof (shake)	William Woolford	Lyle Comeman	Jayson	7/30/76
7/21/76	B. \$ 400	D-5631 \$ 10	Dry-rot repair work	Victor Hickereson P.O. Box 15281 L.A.	Valley Termite/Pest Control/4080 24th St MS/INSP. REG. 10/23/76	Jayson	7/30/76
10-2-79	M.P.E. \$3,500.00	G 9962 \$105.00	Heat A/C	Moses Santanna, same	Kaiser, Heating A/C 5800 Auburn Blvd. 95841	Jayson	10/19/79

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
D-5518	R 450 F 419	D-5631	R 450 F 554	D-5518	R 596 F 207
G-9962	R 596 F 207	D-5518	R 596 F 207	G-9962	R 596 F 207
D-5631	R 450 F 554	D-5631	R 450 F 554	D-5631	R 450 F 554