

Q180 7480-487

| | | | | | |
|--------------|--------------------------|--|-----------------|---------------|-------------------------------|
| Lot 194 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$46.00 |
| Glenbrook #2 | | TYPE BUILDINGS | | | Q184 7524 |
| PERMIT NO. | LOCATION | | | | A-1 |
| F-2775 | 2916 - Terilyn Street | | | | |
| DATE | PURPOSE | OWNER | | | Plan 401LA |
| Jan 12-66 | Const. dwlg. & att. gar. | FWV, Inc. 2777-Alvarado St., San Lean | | | |
| ZONE | ARCH'T | /dr | | | |
| R-1 | CONTR | Besco | same | 483-4300 | |
| VAL. | \$12,400. | STORIES | ROOMS | APTS. | 497-gar. SIZE 1212 sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | 2-10-66 | Hammerson | | | |
| JOIST | 2-16-66 | Chapin | | | |
| FRAME | 3-8-66 | Hammerson | | | |
| SHEET ROCK | 2-14-66 | Callaway | | | |
| FINAL | 4-15-66 | C. Hammerson | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |