

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <b>6895</b>	LOCATION <b>1070-2<sup>nd</sup> St.</b>
DATE <b>9/13/30</b>	PURPOSE <b>Concrete Floor in Rm</b>
ZONE <b>In Com</b>	OWNER <b>G. P. S. Shakeris</b>
	ARCH'T
	CONT'R <b>Owner</b>

VAL. <b>200.</b>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

1137  
 BUILDING DIVISION  
 100 N. 3rd St.  
 PHOENIX, ARIZONA

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="333 826 487 871"><b>COMPLETED AND O.K.</b></p> <p data-bbox="1141 852 1281 871"><b>INSPECTOR</b></p>