

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>9916</b>	LOCATION <b>3927-1/2 Ave</b>			
DATE <b>9-23-32</b>	PURPOSE <b>Remodel &amp; general repairs to dwlg</b>			
ZONE <b>2-Family</b>	OWNER <b>Geo. H. McLaughlin</b>			
	ARCH'T <b>Geo. H. McLaughlin</b>			
	CONT-R <b>Peas W. Henry &amp; Leach</b>			
VAL. <b>400 00</b>	STORIES	ROOMS	APTS.	SIZE

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK--REMARKS
10/4-32	2 <sup>nd</sup> Jump Frame by P.H. Punter
11/28-32-3	" " " " " " P.H. Punter
	<p data-bbox="307 853 457 899">COMPLETE AND O. K.</p> <p data-bbox="1090 878 1250 899">INSPECTOR</p>