

R-284 F65

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$5.00

TYPE BUILDINGS

PERMIT NO. G-7317	LOCATION 529 - San Antonio Way	A-1 (3)
DATE 6-25-70	PURPOSE Repair pest damage to dwelling	
	OWNER J.L.Thompson, 4620 Del Rio Rd.	
ZONE	ARCH'T	
	CONT'R Orchard Supply Co, P.O.Box 956, Sacto.	

VAL. \$400.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 446-7821
FORM	6-29-70	<i>[Signature]</i>		
JOIST				
FRAME				
SHEET ROCK				
FINAL	7-8-70	<i>[Signature]</i>		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK INSPECTOR