

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

\$6.00

TYPE BUILDINGS *R71 F 591*

PERMIT NO. D-6066	LOCATION	364 - Santa Ynez Way		A-1
DATE Jun 23-60	PURPOSE	Repair termite damage to dwelling		
ZONE R-1	OWNER	H. Young	Same	
	ARCH'T		GI 8-1882	
	CONT'R	Valley Termite Co. 1617-18th St.		
VAL. \$750.	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	INSPECTOR		
FORM				
JOIST				
FRAME	<i>6-27-60</i>	<i>Berry</i>		
LATH				
FINAL	<i>7-8-60</i>	<i>Berry</i>		

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
	<p data-bbox="340 844 476 896">COMPLETE AND OK</p> <p data-bbox="1164 865 1307 896">INSPECTOR</p>