

R205 F115

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

DOUBLE FEE

PERMIT NO. F-5597		LOCATION 4000 - San Carlos Way		A-4	
DATE Oct 12-66		PURPOSE Repair termite damage to dwelling			
ZONE R-1		OWNER Stella Zaidel same			
ARCH'T		CONT'R Dale's Termite 4343-Marconi 483-5386			
VAL. \$300.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	8-13-67	Dana Fuller			

0.27

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11/2/66	Pt Final - Refurnish. Replumbing. Repair
COMPLETE AND OK	INSPECTOR